

CITY OF SAN MARCOS ADA TRANSITION PLAN SIGNALIZED INTERSECTION ASSESSMENT AND COMPLIANCE REPORT

Location ID: 000000172 North-South Cross Street: IH 35 SBFR East-West Cross Street: AQUARENA SPRINGS DR Location Details

Signalized Intersection: YES Accessible Features: NO Pedestrian Features Accessible: NO



 Date of Evaluation:
 6/27/2014

 Latitude:
 29.892737
 Longitude:
 -97.913717

 https://maps.google.com/maps?t=h&g=29.892737+-97.913717

Summary of Compliance

| Ramp Elements | Curb ramp provided where an accessible route crosses a barrier: | YES |
|-------------------------------|---|-----|
| | Is the slope of the ramp 1:12 or less: | YES |
| | Transition from curb ramp slope to roadway free from abrupt changes, no greater than 1:20: | YES |
| | Ramp is at least 36" wide: | YES |
| | Ramp surface is stable, firm, and slip resistant: | YES |
| Flare | Flares (if present) are 1:10 or less measured along the curb line; or If landing at top of ramp is not provided flares are 1:12 or less: | YES |
| Detectable Warning Surface | | N/A |
| | Curb ramp is located such that it does not project into roadway or parking aisles: | N/A |
| | Detectable warning is present: | YES |
| | DWS maintains correct geometric controls; 0.9" diameter domes, 0.2" in height, spaced at 2.35" and visually contracts adjacent ramp surface: | YES |
| Special Ramps | Ramp maintains defined edges parallel to direction of pedestrian travel; maintains 4'x4' turning pad contained in crosswalk; flared sides 24" segment on each side of ramp within crosswalk lines: | N/A |
| | Ramp is located so they will not be obstructed by parked vehicles: | N/A |
| | Ramp wholly contained within the crosswalk lines: | YES |
| | If island is present; Island maintains a cut through at street level or ramps on either side with landing between them: | YES |

7/2014





CITY OF SAN MARCOS ADA TRANSITION PLAN SIGNALIZED INTERSECTION ASSESSMENT AND COMPLIANCE REPORT

Location ID: 000000172 North-South Cross Street: IH 35 SBFR East-West Cross Street: AQUARENA SPRINGS DR

Location Photos





7/2014

